



*(Figure 3: Replacement baffle installed in tank prior to completion of water blasting and painting. Note the extensive corrosion on the tank wall)*