



*(Figure 3: Completed concrete repairs to the tank bund walls - view facing north east.)*