

Six thumb screws removed and vehicle "hood" is rotated up and back on hinges to allow easy access the critical electro-mechanical components inside.




FIG. 4B